

US EPA RECORDS CENTER REGION 5



482105

Pete white file
KOT Petroleum
transenvironmental
file O/H
david

July 18, 1980

Mr. Thomas J. Ross
Mae Ross & Company
16500 North Park Drive
Suite 110
Southfield, Michigan 48075

Dear Mr. Ross:

Attached is a copy of the laboratory results you requested. No detectable PCB's were found in any of the samples. However, due to interference, the detection limits were raised to high levels. Pesticide analysis was also performed on the samples. The sample from Tank #1 showed small levels of Endrin and Dieldrin. In the flash point test one of the samples flashed at 70°F. Our laboratory also ran BTU values on all of the samples.

If you have any questions you may contact me at (517) 373-2794.

Very truly yours,
WATER QUALITY DIVISION

Peter Ollila
Water Quality Specialist
Oil & Hazardous Materials Control
Section

I appreciate that your time is a very scarce resource in your new position. However, in view of the fact that there are many environmental problems in the State and that we are here to remedy them, we would appreciate meeting you.

cc: D. Dennis
Files ✓